



THIDUSTIFITY IF GRANDE DECATEVATORATE

(



www.1987machinery.com

DANGER! EXTREMELY FLAMMABLE AEROSOL. VAPORS MAY CAUSE FLASH FIRE. CONTENTS UNDER PRESSURE. VAPOR HARMFUL.

See other cautions on back panel.

NET WEIGHT 15.0 OZ (425 g)

FEATURES AND BENEFITS

Fast acting — cuts through rust, dirt, scale • Fine lubrication for tight fitting parts • Reduces pounding, tugging and breakage • Leaves anti-rust film • Safe on metals, alloys, and rubber • Safe on most painted surfaces

Freeing fasteners, nuts, bolts, studs, pins, valves, pipe couplings, machine parts, etc. • Effective for all rusted and corroded

DIRECTIONS

- 1. For best results, use when can is between 40°F and 90°F (21°C and 32°C). Protect surrounding areas from spray mist.
- 2. Shake can briefly before use.
- 3. Spray surface with steady even strokes at a distance of 6 to 8 inches (15 to 20cm). For pinpoint application, use extension tube.



- 4. If clogging develops, turn sprayhead 1/4 turn or remove and clean sprayhead slot. DO NOT stick pin or other objects into can opening. With can and sprayhead pointed away from you, reinsert sprayhead with a gentle twisting motion.
- 5. Completely empty cans may be recycled or disposed of with regular trash. Dispose partially empty cans responsibly. DO NOT incinerate or compact.

Contains: Acetone 67-64-1, Kerosene 8008-20-6, Propane 74-98-6, N-Butane 106-97-8, Glycol Ether EP 2807-30-9. OTHER INGREDIENTS: "Contents Partially Unknown", Mineral Oil, White 8042-47-5, Mineral Oil 8012-95-1. Petrolatums.



DANGER! Extremely flammable aerosol. Pressurized container: may burst if heated. Causes serious eye irritation. May cause drowsiness or dizziness. May cause damage to organs through prolonged or repeated exposure.



Prevention: Pressurized container: do not pierce or burn, even after use. Use only with adequate ventilation. Do not breathe dust/vapors/spray mist. Avoid contact with eyes/skin/ clothing. Wear protective gloves/clothing/glasses. Keep away from heat/sparks/open flames/ hot surfaces. Do not eat/drink/smoke when using this product. Do not spray on naked flame or other ignition sources. Response: In case of fire, use extinguishing powder or water spray. Immediately contact a doctor or POISON CONTROL CENTER if you feel unwell. If medical attention is needed, have product label at hand. IF IN EYES: Rinse with water for several minutes. Remove contact lenses if present. If eye irritation persists seek medical attention. IF SWALLOWED: Rinse mouth with water. Do not induce vomiting. IF INHALED: Remove to fresh

air. IF ON SKIN: Wash thoroughly with water. Remove all contaminated clothing. Storage: Store locked up. Protect from sunlight and do not expose to temperatures exceeding 50°C/122°F. Disposal: Dispose of product in accordance with local/regional/national/international regulations. Additional Precaution Statements: Vapors may ignite explosively and cause a flash fire. Prevent buildup of vapors by opening windows and doors to achieve cross ventilation. Reports have associated repeated and prolonged occupational overexposure to solvents with permanent brain and nervous system damage. Intentional misuse by deliberately inhaling the contents may be harmful or fatal. In cases where short and/or long term overexposure conditions exist, a charcoal filter respirator should be worn. Follow respirator manufacturer's directions for use.

KEEP OUT OF REACH OF CHILDREN · Read Safety Data Sheet Before Use



www.1987machinery.com

4300 Shady Ln., Huntingtown, MD 20639

